25X1 Approved For Release 2003/08/11: CIA-R	25X1 IDF82-00457R003300210002 -7
CENTRAL INTELLIGENCE	AGENCY REPORT NO.
INFORMATION F	REPORT CD NO. 25X1
COUNTRY USSR (Ukrainian SSR)	DATE DISTR 16 Sentember 1949
SUBJECT Aircraft Engine Plant in Zaporozhe	FIDENTIAL NO. OF PAGES 2
PLACE ACQUIRED 25X1	NO. OF ENCLS. (LISTED BELOW)
DATE OF INFO. 25X	SUPPLEMENT TO 25X1 REPORT NO.
THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL AFFENSE OF THE UNITED STATES WITHIN THE MEASHING OF THE REPIGABLE ACT SO U. S. C., SI AND JR, AS ARRENDED, ITS TRANSLIBBION OR THE EXPLAITOR OF THE CONTENES IN ANY MARKET OF AN UNAUTHORIZED PERSON IS PROBLEMED OF THE CONTENES IN ANY MARKET OF AN UNAUTHORIZED PERSON IS PROBLEMED OF THE PROBLEMED OF THE PROBLEMED.	THIS IS UNEVALUATED INFORMATION 25X1
l. <u>Location:</u> Several hundred pards ea	st of the ZAPOROZHE (35°15'E/
Plant history: The plant existed by war its production facilities were the heavily damaged plant was 75 per percent of the plant installations to a newly constructed water tower was. This reinforced concrete tower extended feet above grounds diameter, above crete wall, about 3 feet.	rcent reconstructed and 50 were back in production. also nearing completion.
 The plant was presumably controlled is sions arrived from there rather regulations. 	oy a KIEV agency, as commise
4. Plant management: The director of the always wore a uniform. A German States or Silesia), who moved about MVD querters, was employed in the lengtheer from Thuringia was in charge From 15 to 20 ethnic German technical at the plant.	engineer (from the baltic freely and lived in the boratory. Another German
5. Installations: The plant covered ab had the following departments,	out 5,000 x2650 feet and 25X1
Design office Lathe department Punching shop and processing of Assembly shop Foundry Aluminum foundry	Four engine test stands.
CLASSIFICATION SERRET STATE NAVY X NSRB ARMY # X AIR # X FBI	5X1
CONFIDENT	2511 115110, 1 Apr // 25/
Approved For Release 2003/08/11 : CIA-R	Auth: <u>DDA REG. 77</u> DP82-00457R003300210002-7
The state of the s	

CENTRAL INTELLIGENCE AGENCY

CONFIDENTIAL

One unidentified workshop, surrounded by three to four wire fences, was guarded by sentries with watch dogs. A building, noted.

6. Work Force: No exact figures could be given. The number of workers was increased in 1947. About fifty percent of the work force were women. There were also about a hundred Stalin students and from 10 to 20 Germans from the Soviet Zone of Germany. Work was done in three 8-hour shifts. The number of workers on the night shift was very small.

7. roduction

- a. Two types of radial engines, allegedly for fighters. The larger type of engine was shipped by air from the factory airfield. One twin-engine plane picked up finished engines every two days. The smaller type of engine was installed in fighters. This engine was about 15 inches wide, 50 inches long, and 44 inches in diameter. It was probably air-cooled, as no water containers were observed at the test stand.
- b. Occasionally motorcycles were shipped from the plant on trucks.
- c. The four engine test stands were in operation day and night.
- 8. Other observations: The plant was guarded by a special factory guard and EVD personnel, allegedly assigned to the 101st Regiment, which was not stationed in ZAPOROZHE. The EVD guards were mostly young soldiers, from 19 to 20 years old. Five or six officers, including an air force major and a navel officer, were constantly seen at the plant.
- 9. Factory Airfield: Dimensions: 3,300 x 2,650 feet, no runway; loamy soil covered by grass. It was located two miles southeast of the plant; about 2,650 feet west of the military

25X1 10. the ZAPOROZHE Aircraft Ingine Plant was located about 1,650 feet east of the ZAPOROZHE railroad station. The plant was 75 per reconstructed. Radial engines allocated about 1,650 feet east of the ZAPOROZHE railroad station.	
WOUND TROOP CARL OF THE VIOLENCE WASTERS JULIAN	
reconstructed. Radial engines allowable fautured station. The plant was 75 pe	
reconstructed. Radial engines, allegedly for light aircraft, are producedo the manufacture of motorcycles had been suspended for	
some time. Motorcycles were not seen.	

25X1 Comment:

a. The data contained in par 1 thru 9 on the ZAPONOZHE -ir-craft Engine Plant have been confirmed by several more recent reports.

b. Paragraph 12 (reported period: September 1948) shows that the reconstruction work made slow progress but that the stop-gap production of motorcycles has been suspended. This may type cannot be determined from the report. Of the small radial engines only the N-11 (5 cylinders) and the ASh-21 of double-row radial engines similar to the BWW-801 is also concordantly mentioned.

SECRET 25X1 CONFIDENTIAL